1962 1962 1962 1983 1963	SECRET		A 1	
25X4cm ENRECTOR RETURN CSA (1-2/-3-4-5-6-	7=8-9-1Ø)	2E)	PRIORITY	
TOR: Ø121Z Ø3 NOV	1 1962	2.	IN 54389	
25×1:0 PRITY	nto	CFF;		25X1

- 1. REFERENCE YOUR TELEPHONE CONVERSATION CONCERNING J-58 WINDMILL-ING RPM PROBLEM.
- 2. DURING THE ATTEMPTED RESTART OF J-58 AT 36,000 FEET AND M 1.2 NOTHING HAPPENED AND THE AIRCRAFT WAS DECELERATED FROM 1.2 TO .88 AND ALTITUDE REDUCED TO 26,000 FEET. DURING THIS PERIOD 6 PROCEDURE RESTARTS WERE ATTEMPTED BEFORE A RELIGHT OCCURRED AT 25,000.
- EELOW THE RATING SIVEN BY PAW. THIS REDUCES OUTPUT OF HYDRAULIC FUNCTION AND ELECTRIC GENERATORS TO THE POINT OF BEING INOPERATIVE AND WILL FRIBABLY HEAR PHE EMSTALLATION OF AN AIR TURBINE GENERATOR AND PUMP TO ARRUPE SERVICES SHOULD BOTH EMSINES BLOW OUT. THIS IS A VERY FOSSIBLE OCCURRENCE AT FULL MACH NUMBER AND ALTITUDE CRUISE. IN NW
- TEB SYSTEM IS WORKENS AND IT IS DIFFIGURE TO CONDEMN THE ENGINE FOR

of the Community of the

SECRET

25X↑		• (1)
20/1	SECRET	
	CSB 545399	5282 1 w3
_		
	NOT STARTING WHEN THE PROBLEM MAY BE IGHT	CION FAILURE. ACCORDINGLY
25X1	1 WITH CONCURRENCE LAC IS DESIG	in ing a manhal teb system / yes
	TO ASSURE IGNITION.	
	5. AS A RESULT OF THE ABOVE RESTART EX	PERIENCE PAN HAS COME
	UP WITH A MODIFIED RESTART SPEED-ALTITUDE	ENVELOPE WHICH IS THE
	MEXI THING TO UNACCEPTABLE. THE PROBLEM I	IS STILL OPEN AS FAR AS I
	CAN SEE AT THIS TIME.	12/
	ENC OF MESSAGE	
	the for the space	WWW. AS FAR AS I
	relians windmit yes	
	rellynia winding - ves	70
	CORVO	
	.	
	Note. Politie & N.	10-0 (1.20
	100, Relies C 14W	or sur
	soporale proble	lees,
	of the same Control	· o lla a un l
	Note: Relites & Nw superate proble don't confus	e there's
	Relite = f (Pb, Tx, Ta, E	15 Siring) not + (NW=170)
V	Nor = f (Turb. Wa & Mor.	Fom

Approved For Release 2004/05/13 : CIA-RDP89B00980R000300070075-3